## JW5002N -Deluxe type Fiber Inspection& Cleaning Kits

|     | = = =  |              |   |
|-----|--|--------------|---|
| No. | Tool Name  | Qty          | Function  |
| 1   | JW5005N Probe Fiber<br>Microscope with 200x<br>magnification | 1            | both patch cords and bulkhead adapters. Including patch cords |
| 2   | JW3105P Visual Fault Locator                                 | 1            | Visually checking breakpoints,                                |
| 3   | JW5006 Fiber Connector<br>Cleaner(QAM Cleaner)               | 1            | To perform patch cords cleaning.                              |
| 4   | JW5008 Pen-style Fiber<br>Cleaner, 2.5mm&1.25mm              | 1pcs of each | To perform bulkhead/in-adaptor ferrule cleaning               |
| 5   | Alcohol Bump Bottle  | 1            | Cleaning the fiber  |
| 6   | Cleaning Cotton Swabs  | 1            | cleaning the fiber adapter interface and sleeve               |
| 7   | Carrying case  | 1            | To place above items  |

## Tool Kits Picture



It includes everything you need to perform inspection and cleaning of the fiber end faces, including Fiber Patch Cords, Bulkhead connections/In-adaptor ferrules and fibers in preparation for splicing applications.