JW5003 - Cable Inspection & maintenance tool kits

No.	Tool Name	Qty	Function	Tool Kits Picture
JW5003 Cable	e Inspection & maintenance too	ol kits compose	d of mini power meter, fiber	
1	Optical Fiber Ranger(Fiber Cable Locator)	1	Detects the faults location for the long and short distance	13
2	Small Alcohol Bottle(5ml only)	1	storing alcohol	ARROD AR
3	Optical Fiber Cleaver	1	Cleave the fiber	
4	Mini Optical Power Meter	1	Act optical power measurements on fibers I ake apart or assemble the	
5	Hexangular wrench	1	Take apart or assemble the splicing closure	
6	CFS-2 Fiber optic stripper	1	Strip the jacket or coated fiber	
7	wire-cutter	1	Cut the strengthened cable core	
8	Monkey Wrench	1	Take apart or assemble the splicing closure	2 4 6 7 8 9 10
9	Cutter	1	Strip the fiber(extra refill cutter)	
10	Cross Screwdriver	1	Take apart or assemble the splicing closure	
11	Straight Screwdriver	1	Take apart or assemble the splicing closure	
12	User manual	1	Operating Instruction and maintenance	
13	Hard Carrying Case	1	Contain all above tools	
			·	